

ELEVEN CARS MAX LEAVING WHITE HALL

NOTE: Operator has map of all spotting locations.

1. In Hood, sign register, check with operator for orders, take water, wait for clearance.
2. In Swift Run, stop, sign register, check with operator for orders.
3. In Furnace, take water.
4. In Stanley, place cars on N&W interchange (back track), turn engine, terminate.